


Windshield Damage Defined






Examples of Windshield Damage Pass and Fail Conditions

❌ Fail	✅ Pass
1. Crack through one layer that extends more than 50 mm (2") into the area swept by wipers. 2. Star chip larger than 13 mm (1/2") in diameter in area swept by wipers.	3. Crack extends less than 50 mm (2") into the area swept by wipers. 4. Star chip smaller than 13 mm (1/2") in diameter in area swept by wipers. 5. Crack through one layer that is more than 50 mm (2") long, but outside the area swept by wipers. 6. Star chip larger than 13 mm (1/2") in diameter, but outside the area swept by wipers.

How to measure stone or shot damage

Stone or shot damage to the windshield causes damage rings or cracks to run outside of the damaged area. To take an accurate measurement, measure across the two largest extending cracks or ring.

Other Windshield Requirements

❌ Fail		✅ Pass	
Driver's side	Passenger's side	Driver's side	Passenger's side
 Decal extends into area normally swept by the wipers.		 Decals do not extend into area normally swept by the wipers.	
 Discoloration is greater than 10% of the total glass area, or if sandblasting impairs driver's vision.		 Decal does not extend into area normally swept by the wipers.	
 Decal or vision restricting band extends from top or bottom into area normally swept by wipers			

After market sunscreen or reflective material on vehicles

In Saskatchewan, the use of after-market window tinting, sunscreen or reflective material, other than that applied by the glass manufacturer, is prohibited on both the windshield, and front side windows of a vehicle.

For further information, please contact Carrier & Vehicle Safety Services at 1-800-667-8015 ext. 6188.